



Invicta Arboriculture
Tree and Woodland Consultancy

Arboricultural Condition Report

York and Albany Close Peace Garden
Walmer
Kent
CT14 7RR

14th June 2024



Mr David Sephton Tech Cert (Arbor. A)
Tel: 01303 266958 | Mobile: 07810 783853 | Email: invictaarb@icloud.com



1 INTRODUCTION

- 1.1 **Instruction:** I am instructed by Walmer Town Council to undertake a comprehensive hazard assessment tree survey at the York and Albany Close Peace Garden, Walmer, CT14 7RR and to provide an arboricultural report on any trees which are considered to pose an unacceptable risk to the health and safety of users of the site and adjacent properties.
- 1.2 **Qualifications and experience:** I have based this report on my site observations, and I have come to conclusions in the light of my experience as an arboriculturist.
- 1.3 **Documents and information provided:** I was provided with a map of the site.
- 1.4 **Relevant background information:** This report was commissioned by Walmer Town Council in order to fulfil its duty of care in relation to its tree stock at the York and Albany Peace Garden.
- 1.5 **Collection of data:** The survey was carried out using the following inspection aids:
 - Sounding mallet to detect cavities.
- 1.6 **Scope of this report and limitations:** This report is only concerned with the structural and physiological condition of any trees found that are considered to pose an unacceptable risk to the users of the site and adjacent highway and are shown on the site plan included at appendix A. This plan is for illustrative purposes only and should not be used for directly scaling measurements. All the relevant information on it is contained within this report. It takes no account of any other trees. It includes a detailed assessment based on the site visit.

This report is only concerned with any trees found that have clear, observable and detectable defects. All trees present within the site boundaries have been assessed from accessible points at ground level. Trees that are not listed within the schedule were considered to display good overall form and vitality with no significant visible structural or physiological defects; that is not to say that their condition may change over time (for example, internal decay that was undetectable, suspected or otherwise unforeseeable at the time of inspection could quite reasonably advance rapidly between inspections and lead to the structural failure of the affected part), however at the point of inspection they were deemed to pose an acceptable risk.

Trees and shrubs are living organisms whose health and stability can change rapidly especially following extreme weather events and therefore the recommendations given in this report are valid for a period of twelve months.

All tree works should be carried out to B.S. 3998:2010 *Recommendations for Tree Work* or as modified by more recent research. It is advisable to select a contractor from the local authority list and preferably one approved by the Arboricultural Association. Their Register of Contractors is available free from The Malthouse, Stroud Green, Standish, Stonehouse, Gloucestershire, GL10 3DL – 01242 522152 and can also be found on their website: <http://www.trees.org.uk/find-a-professional/Directory-of-Tree-Surgeons>.

Visual Tree Assessment.

Location: York and Albany Close Peace Garden.

Name: Mr D.Sephton

Date: 14th June 2024

Client: Walmer Town Council

Tree No	Species	Condition	Recommendations	Work Priority	Cost
		All trees present within the boundaries of the site display good overall form and vitality with no significant visible structural or physiological defects and are currently considered to pose an acceptable risk to users of the site and adjacent properties.	None	N/A	

Work Priority: 1= Urgent (within 24 hours). 2= High Priority (within three months). 3= Medium Priority (within six months).

Appendix A – Site Plan:

